





CR NUMBER 22-17137	ACCIDENT DATE 10/9/22	ACCIDENT TIME 1700	DAY OF WEEK SUN	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) UHaul 1227 W main St Kent, OH 44240			WEATHER No Adverse	

VEHICLE NO. 1					VEHICLE NO. 2 (OR PROPERTY DAMAGED)				
DRIVER LAST	FIRST	MIDDLE	DOB		DRIVER LAST	FIRST	MIDDLE	DOB	
Debosier	Adam	Christopher	11/8/91		UHaul Business Sign				
ADDRESS 2459 Waterford Pointe Dr					ADDRESS				
CITY, STATE, ZIP Kent, OH 44240			PHONE NUMBER		CITY, STATE, ZIP			PHONE NUMBER	
DRIVER'S LICENSE # NI MRFP				STATE FL	DRIVER'S LICENSE NUMBER				STATE
VEHICLE OWNER'S NAME LAST FIRST MIDDLE UHaul Co. of Arizona					VEHICLE OWNER'S NAME LAST FIRST MIDDLE				
ADDRESS 2727 N central Ave					ADDRESS				
CITY, STATE ZIP Phoenix, AZ 85004			PHONE NUMBER 330-673-5585		CITY, STATE, ZIP			PHONE NUMBER	
VEHICLE	YEAR	MAKE	MODEL	COLOR	VEHICLE	YEAR	MAKE	MODEL	COLOR
	2019	Ford	Econoline	white					
LICENSE PLATE		NUMBER	STATE		LICENSE PLATE		NUMBER	STATE	
		AJ31892	AZ						
INSURANCE COMPANY Amerco					INSURANCE COMPANY				
PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT 					PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT				

DESCRIBE HOW ACCIDENT OCCURRED
 Unit 1 was driving EB through the parking lot and struck the UHaul Business Sign near the roadway.
 Both the truck and sign were damaged. The driver of unit 1 has Geico Insurance.

OFFICER / SUPERVISOR SIGNATURE  #251 / 14	SKETCH HOW ACCIDENT OCCURRED 	INDICATE NORTH BY ARROW  *Not to Scale