

CR NUMBER 20-9746	ACCIDENT DATE 6-21-20	ACCIDENT TIME 0900-0945	DAY OF WEEK SUN	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 1600 S. Water St (Marc's Lot)			WEATHER Clear	
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB	DRIVER LAST FIRST MIDDLE DOB			
ADDRESS	ADDRESS			
CITY, STATE, ZIP	CITY, STATE, ZIP			
PHONE NUMBER	PHONE NUMBER			
DRIVER'S LICENSE NUMBER	DRIVER'S LICENSE NUMBER			
STATE	STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE	VEHICLE OWNER'S NAME LAST FIRST MIDDLE			
ADDRESS	ADDRESS			
CITY, STATE, ZIP	CITY, STATE, ZIP			
PHONE NUMBER	PHONE NUMBER			
VEHICLE YEAR MAKE MODEL COLOR	VEHICLE YEAR MAKE MODEL COLOR			
LICENSE PLATE NUMBER STATE	LICENSE PLATE NUMBER STATE			
INSURANCE COMPANY	INSURANCE COMPANY			
PARTS OF VEHICLE DAMAGED	PARTS OF VEHICLE DAMAGED			
DESCRIBE HOW ACCIDENT OCCURRED Unit 1 was parked unoccupied at 1600 S. Water St between 0900 and 0945 hours on 06-21-20. During that time frame, several small scratches were made on the driver's side door below the door handle and along the trim at the bottom of the door frame as if a grocery cart had sideswiped the vehicle. Manager at Marc's advised there are no cameras that cover the area where the vehicle was parked.				
OFFICER/SUPERVISOR SIGNATURE [Signature] #216			SKETCH HOW ACCIDENT OCCURRED 1600 S. Water St	
			INDICATE NORTH BY ARROW NT *Not to Scale	