

CR NUMBER 22-19046	ACCIDENT DATE 11-10-22	ACCIDENT TIME	DAY OF WEEK THU	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 609 S. LINCOLN BUILDING "O"			WEATHER CLEAR / SUNNY	
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB SCHEUER, ETHAN T. 10-24-00	DRIVER LAST FIRST MIDDLE DOB MOORE DAVID H. 11-26-71			
ADDRESS 1480 QUEEN ANNES GATE	ADDRESS 320 S. DEPEYSTER ST.			
CITY, STATE, ZIP WESTLAKE, OH. 44145	CITY, STATE, ZIP KENT, OH. 44240			
PHONE NUMBER	PHONE NUMBER			
DRIVER'S LICENSE NUMBER	DRIVER'S LICENSE NUMBER			
STATE OH	STATE OH			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE SAO	VEHICLE OWNER'S NAME LAST FIRST MIDDLE CITY OF KENT			
ADDRESS	ADDRESS 930 OVERHOLT RD.			
CITY, STATE ZIP	CITY, STATE, ZIP KENT, OH. 44240			
PHONE NUMBER	PHONE NUMBER			
VEHICLE YEAR MAKE MODEL COLOR 13 SUBARU IMPREZA MAROON	VEHICLE YEAR MAKE MODEL COLOR 16 FORD EXPEDITION WHITE			
LICENSE PLATE NUMBER STATE JVB-3951 OH.	LICENSE PLATE NUMBER STATE 1FMJU1G17GEF23457- OH. CAR 1			
INSURANCE COMPANY ALLSTATE - 826632688	INSURANCE COMPANY LOVE- PKG 81310292			
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT BUMPER	PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT NONE			
DESCRIBE HOW ACCIDENT OCCURRED				
<p>UNIT ONE BACKED FROM A PARKING SPACE, FAILING TO SEE UNIT TWO. UNIT ONE STRUCK THE PUSH BUMPER OF UNIT TWO, CAUSING NO OBSERVED DAMAGE. UNIT ONE HAS MINIMAL DAMAGE TO THE CENTER REAR BUMPER.</p>				
OFFICER / SUPERVISOR SIGNATURE [Signature]			SKETCH HOW ACCIDENT OCCURRED PROVENCE APARTMENT COMPLEX ASPHALT APARTMENT PARKING LOT	
			INDICATE NORTH BY ARROW N 609 S. LINCOLN BUILDING "O"	
			* NOT TO SCALE	