




CR NUMBER 24-4941	ACCIDENT DATE 4/6/24	ACCIDENT TIME 1200	DAY OF WEEK SAT	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Starbucks 1005 E main St.			WEATHER No Adverse	
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB Amigo melody Ann 2/15/95	DRIVER LAST FIRST MIDDLE DOB PARKED vehicle			
ADDRESS 724 Stinaff St	ADDRESS			
CITY, STATE, ZIP Kent, OH 44240	CITY, STATE, ZIP PHONE NUMBER			
DRIVER'S LICENSE NUMBER STATE OH	DRIVER'S LICENSE NUMBER STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Same as driver	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Stanoch Terrence Peter			
ADDRESS	ADDRESS 2491 Fawn Chase			
CITY, STATE ZIP PHONE NUMBER	CITY, STATE, ZIP PHONE NUMBER Richfield, OH 44286			
VEHICLE YEAR MAKE MODEL COLOR 2014 Hyundai Santa Fe Black	VEHICLE YEAR MAKE MODEL COLOR 2015 Honda Accord Gray			
LICENSE PLATE NUMBER STATE G2N1359 OH	LICENSE PLATE NUMBER STATE HXJ7209 OH			
INSURANCE COMPANY State Farm	INSURANCE COMPANY Safeco			
PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT 	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 			
DESCRIBE HOW ACCIDENT OCCURRED Unit 2 was parked and unoccupied in the Starbucks parking lot. The driver of Unit 1 struck Unit 2 when attempting to park in the spot to the left of the vehicle				
		SKETCH HOW ACCIDENT OCCURRED *Not to Scale Starbucks 1005 E main St Tropical Smoothie Cafe UH Urgent Care 		
OFFICER /SUPERVISOR SIGNATURE Ofc [Signature] #251		#216		