






CR NUMBER 22-11914	ACCIDENT DATE 7-16-22	ACCIDENT TIME 2248	DAY OF WEEK SAT	<input type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input checked="" type="checkbox"/> DARK	
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Parking lot across Franklin Ave From the Pub			WEATHER N/A		
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)			
DRIVER LAST FIRST MIDDLE DOB Lewis Scott Matthew 4-26-89	DRIVER LAST FIRST MIDDLE DOB Unoccupied				
ADDRESS 5209 ST HW 5		ADDRESS			
CITY, STATE, ZIP PHONE NUMBER Kovarna OH 44266		CITY, STATE, ZIP PHONE NUMBER			
DRIVER'S LICENSE NUMBER STATE OH		DRIVER'S LICENSE NUMBER STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Rand H Limited LLC		VEHICLE OWNER'S NAME LAST FIRST MIDDLE Torosian, Arek			
ADDRESS 1202 Sellman Dr		ADDRESS 33046 Lisa Ln			
CITY, STATE, ZIP PHONE NUMBER Akron OH 44333		CITY, STATE, ZIP PHONE NUMBER Solon OH 44139			
VEHICLE YEAR MAKE MODEL COLOR 2020 Chevy 2500 white	VEHICLE YEAR MAKE MODEL COLOR 2019 Honda Civic Blue				
LICENSE PLATE NUMBER STATE PKA7473 OH	LICENSE PLATE NUMBER STATE Jay 7981 OH				
INSURANCE COMPANY		INSURANCE COMPANY Progressive			
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT 	PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 				
DESCRIBE HOW ACCIDENT OCCURRED Unit 1 backed in to Unit 2. The inside wheel well of unit 1 struck the right side of Unit 2's bumper. Unit 2 was parked					
OFFICER/SUPERVISOR SIGNATURE 			SKETCH HOW ACCIDENT OCCURRED		
					INDICATE NORTH BY ARROW  N MTS
			Private Parking lot		