CR NUMBER	ACCIDENT	ACCIDE	NT.	DAVOE		
21-6536	DATE 4-26-21	TIME /	705	DAY OF WEEK MON	DAYLIGH DAWN O	IT R DUSK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) WEATHER						
777 STO	W 57			1	O A DVE	RSE
VEHICLE NO. 1  DRIVER LAST FIRST MIDDLE DOR			VEHICLE NO. 2 (OR PROPERTY DAMAGED)			
UNDUA PROMILE			DRIVER LAST FIRST MIDDLE DOB RAPP MELISSA ANN 1-24-80			
ADDRESS	01 2/1010 /	-31-91	ADDRESS	IELISSA	ANN 7-	24-80
7219 BIRCHVIEW DR			655 HAZEN AVE #2			
CITY, STATE, ZIP PHONE NUMBER  RAVENNA, OH 44266			CITY, STATE, ZIP  RANENNA, OH 44266  PRINTER'S LIGHTS AND ASSETTIONS ASSETTIONS AND ASSETTIONS ASSETTIONS ASSETTIONS ASSETTION			
DRIVER'S LICENSE NUMBER	017	ATE H	DRIVER'S LICEN	ISE NUMBER	STA	
VEHICLE OWNER'S NAME  SAME	LAST FIRST MIC	DDLE	VEHICLE OWNE	R'S NAME LAS		
ADDRESS	ADDRESS					
CITY, STATE ZIP	PHONE NUMBE	ΞR	CITY, STATE, ZI	p	PHONE NUMBE	R
VEHICLE YEAR MA		LOR ACK	VEHICLE YE	EAR MAKE	MODEL COL	OR BLUE
ENW	JMBER STATE		LICENSE PLATE			DLVL
INSURANCE COMPANY PROGRESSIVE # 2/700225			INSURANCE COMPANY, GENERAL #OH5579633			
PARTS OF GRONT VEHICLE DAMAGED	REAR LEFT BY	RIGHT				IGHT
Unit 1:2 were	occurred traveling in	the		let of	777 (Lau)	1/2/1
Unit 1:2 were traveling in the parking lot of 777 Stow St. Unit 1 was parked N/w facing. Unit 2 was traveling N/B. Unit 1 backers						
out of a parking space and struck Unit 2. Unit 1 caused						
a property damage only private property crash.						
J J J J J J J J J J J J J J J J J J J						
			SKETCH HOW	ACCIDENT OCCUP	RRED	INDICATE
			1001 10	SCALE		NORTH BY ARROW
			-	74		
			-		(2)	777
			1		1	STOW
			-		`	ST
OFFICER /SUPERVISOR SIGN	NATURE LA. Shund #	10.8	1 _			
chinal selection 50	LT. // IMM	40		TOW ST		1